

# ***VT 15/ETHAN ALLEN AVE SCOPING REPORT***

Essex, Vermont

October 2009



***Chittenden County  
Metropolitan Planning  
Organization***

---

*Communities working together  
to meet Chittenden County's  
transportation needs*



***Chittenden County  
Metropolitan Planning  
Organization***

---

30 Kimball Ave., Suite 206  
South Burlington, Vermont 05403  
t 802-660-4071  
f 802-660-4079  
[www.ccmppo.org/info@ccmpo.org](http://www.ccmppo.org/info@ccmpo.org)

---

The preparation of this document has been financed through transportation planning funds provided by the U.S. Department of Transportation under the Transportation Equity Act for the 21<sup>st</sup> Century (TEA-21) and by matching funds provided by Chittenden County's 18 municipalities, the Vermont Agency of Transportation, and the Chittenden County Transportation Authority.

Prepared by:



# TABLE OF CONTENTS

---

<b>1.0</b>	<b>INTRODUCTION .....</b>	<b>1</b>
1.1	Project Background .....	1
1.2	Project Study Area .....	1
1.2.1	<i>Recent and Ongoing Plans and Studies</i> .....	2
1.2.2	<i>Planned Improvements for the Project Area</i> .....	3
<b>2.0</b>	<b>EXISTING CONDITIONS .....</b>	<b>4</b>
2.1	Recommended Design Standards.....	7
2.2	Transit Service.....	10
2.3	Pedestrian and Recreational Facilities.....	13
2.4	Parking.....	14
2.5	Utilities.....	15
2.6	Right of Way, Zoning, and Dimensional Standards .....	17
2.7	Existing and Future Traffic Conditions .....	20
2.7.1	<i>Traffic from Other Permitted Developments</i> .....	20
2.7.2	<i>Volume Adjustment Factors</i> .....	20
2.7.3	<i>Future Traffic Conditions</i> .....	22
2.8	Congestion Analysis .....	23
2.8.1	<i>Level of Service Definition</i> .....	23
2.8.2	<i>Level of Service Results</i> .....	24
2.9	Signal Warrant Analysis.....	25
2.9.1	<i>Impact of New Traffic Signal on Vehicle Flow and Safety</i> .....	27
2.10	Vehicle Crashes .....	29
2.11	Environmental and Cultural Resources.....	31
2.11.1	<i>Flood Zones</i> .....	31
2.11.2	<i>Wetlands</i> .....	32
2.11.3	<i>Archaeological Resources</i> .....	33
2.11.4	<i>Historic Resources</i> .....	33
2.11.5	<i>Hazardous Waste Sites</i> .....	34
2.11.6	<i>Rare, Threatened or Endangered Species and Significant Communities</i> .....	36
2.11.7	<i>Public Lands</i> .....	36
2.11.8	<i>Prime Agricultural Soils</i> .....	36
2.12	Permitting .....	37
2.12.1	<i>Act 250 Land Use Permit</i> .....	37
2.12.2	<i>401 Water Quality Permit</i> .....	37
2.12.3	<i>404 Corps of Engineers Permit</i> .....	38
2.12.4	<i>Stream Alteration Permit</i> .....	38
2.12.5	<i>Conditional Use Determination</i> .....	38



2.12.6	Stormwater Discharge Permit.....	38
2.12.7	Shoreland Encroachment Permit .....	38
2.12.8	Endangered and Threatened Species Permit .....	38
2.12.9	VTrans Access Permit.....	38
2.12.10	Categorical Exclusion (CE).....	38
<b>3.0</b>	<b>PURPOSE &amp; NEED.....</b>	<b>39</b>
3.1	Purpose.....	39
3.2	Need .....	39
<b>4.0</b>	<b>ALTERNATIVE INVESTIGATION.....</b>	<b>39</b>
4.1	Development of Alternatives .....	39
4.2	Description of Alternatives.....	40
4.2.1	Alternative 1: No Build.....	40
4.2.2	Alternative 2: Signal Lite.....	40
4.2.3	Alternative 3: Signal Plus .....	44
4.2.4	Alternative 4: Transit Only.....	47
4.3	Evaluation of Alternatives .....	47
4.3.1	Bus Operations.....	47
4.3.2	Ridership .....	48
4.3.3	Arterial Flow .....	48
4.3.4	Safety.....	59
4.3.5	Aesthetics.....	60
4.3.6	Economic Development Potential.....	60
4.4	Evaluation Matrices .....	60
4.5	Preferred Alternative .....	62
4.6	Historic Assessment .....	63

**LIST OF FIGURES**

Figure 1:	Study Area of the Scoping Study.....	2
Figure 2:	University of Vermont Holdings Proximate to the Project Area.....	3
Figure 3:	Westerly View Down VT 15 from Ethan Allen Avenue .....	5
Figure 4:	Easterly View Down VT 15 from Ethan Allen Avenue.....	5
Figure 5:	AADTs in the Study Area .....	6
Figure 6:	Exit of Ethan Allen Avenue onto VT 15 .....	6
Figure 7:	View Down Ethan Allen Avenue Showing Intersection with Dalton Drive.....	7
Figure 8:	Applicable Design Standards .....	8
Figure 9:	VT 15 Cross Sectional Recommendation from the Route 15 Corridor Study.....	9
Figure 10:	CCTA Essex Junction Route .....	10
Figure 11:	CCTA Outbound Route Path & Stop Locations .....	11
Figure 12:	CCTA Inbound Route Path & Stop Locations .....	12
Figure 13:	Permanently Protected Lands Proximate to the Study Area .....	13
Figure 14:	Pedestrian Facilities in the Project Area.....	14



Figure 15: On Street Parking in the Study Area .....	15
Figure 16: Utilities in the vicinity of VT 15/Ethan Allen Avenue .....	16
Figure 17: Land Uses within the Study Area .....	17
Figure 18: Permitted and Conditional Uses in the Historic Preservation – Design Control Zone .....	18
Figure 19: Dimensional Standards .....	20
Figure 20: Other Development Volumes .....	20
Figure 21: Traffic Adjustment Factors .....	21
Figure 22: AM and PM Peak Hour Trips – Raw Count Data.....	21
Figure 23: 2010 AM and PM Peak Hour No Build .....	22
Figure 24: 2020 AM and PM Peak Hour No Build .....	23
Figure 25: Level-of-Service Criteria for Signalized and Unsignalized Intersections.....	24
Figure 26: Signalized LOS Results – AM/PM Peak Hours No Build .....	25
Figure 27: Unsignalized LOS Results – AM/PM Peak Hours No Build .....	25
Figure 28: Signal Warrants at VT 15-Ethan Allen Avenue .....	26
Figure 29: Coordinatability Factor Results.....	27
Figure 30: Distance Between Project Area Intersections .....	28
Figure 31: Excerpt from the NCHRP Crash Reduction Factor Figure.....	29
Figure 32: Crash Locations on VT15, 1997-2006.....	30
Figure 33: Crashes at VT 15/ Ethan Allen Avenue .....	31
Figure 34: Crash Time of Day at Ethan Allen Avenue.....	31
Figure 35: FEMA Flood Insurance Rate Map 100-Year Flood Plain.....	32
Figure 36: Wetlands near Fort Ethan Allen.....	33
Figure 37: VT ANR Active Hazardous Site List-November 2007.....	34
Figure 38: VT ANR Hazardous Sites .....	35
Figure 39: VT ANR Underground Storage Tank Site List.....	35
Figure 40: Agricultural Soils.....	37
Figure 41: No Build Alternative Showing the Outbound Routing of CCTA’s Essex Route .....	40
Figure 42: Signal Lite with Slip Lane.....	42
Figure 43: Signal Lite – no Slip Lane.....	43
Figure 44: Signal Plus with Slip Lane.....	45
Figure 45: Signal Plus – no Slip Lane.....	46
Figure 46: Signalized LOS Results – AM Peak Hour .....	49
Figure 47: Signalized LOS Results – PM Peak Hour .....	49
Figure 48: Signalized LOS Results – AM Peak Hour – 2 Southbound Right Turn Lanes at Susie Wilson Rd .....	50
Figure 49: AM Peak Hour Total Delay Index .....	51
Figure 50: PM Peak Hour Total Delay Index.....	51
Figure 51: AM Peak Hour Total Delay Index - 2 Southbound Right Turn Lanes at Susie Wilson Rd .....	52
Figure 52: AM Peak Hour Total Stops Index .....	53
Figure 53: PM Peak Hour Total Stops Index.....	53
Figure 54: AM Peak Hour Total Delay Index - 2 Southbound Right Turn Lanes at Susie Wilson Rd .....	54
Figure 55: AM Peak Hour Total Travel Time Index.....	55
Figure 56: PM Peak Hour Total Travel Time Index.....	55



Figure 57: AM Peak Hour Total Travel Time Index - 2 Southbound Right Turn Lanes at Susie Wilson Rd..... 56

Figure 58: AM Peak Hour Queues (# cars) ..... 57

Figure 59: PM Peak Hour Queues (# cars) ..... 58

Figure 60: AM Peak Hour Queues Assuming Two Southbound Right Turn Lanes at Susie Wilson Road (cars) ... 58

Figure 61: Turn Lane Warrant for Westbound Right at Ethan Allen Avenue ..... 59

Figure 62: Excerpt from FHWA’s Safety Effectiveness of Intersection Left- and Right-Turn Lanes (2002) ..... 60

Figure 63: Evaluation Matrix – Study Measures ..... 61

Figure 64: Evaluation Matrix – VTrans..... 62

